

**Software Release Note  
AT Version Vx40  
Class B GPRS Release**

## 1 New Features

None.

## 2 Corrected Problems (CP) / Changes in the AT command Description (AT)

Type	Title
CP	AT+WIMEI erase IP feature
CP	wm_gprsOpen function return a wrong value GPRS Not Supported on B40n09gx.2d !
AT	Merge the 2 paragraphs of AT+CCED command (AT001_008)
CP	Pb edevice after a v24switch mode during data transfer
CP	Fax transmission can be interrupted after ending page (first)
CP	Bus constants
CP	New wm_fcmQuery() function
CP	Data transmission is interrupted and data can be lost during the transfer
CP	AT+WBCM=0 can't stop charging
CP	no response to UDP after 25 min of inactivity
CP	Display of +WBCI: 0 in Terminal Emulator when plug off and plug on a demo board
CP	Wrong software version when upgrading from 534e to X40
AT	modif doc AT command +wgprs
CP	MO call failed with NMO I and T3321 running
CP	reset with sms over GPRS
CP	missed SMS CB
CP	Reset when sending SMS with +CGSMS=0 and CGATT=1
CP	AT+COPS operator names formats
AT	<ind> description in AT documentation for AT+CIND
CP	ALITEC: AT+CPOL=,2 during a com
CP	AT+COPS? Bad registration status

### 3 Known Bugs

Title
V42bis -Unable to get connection for V21, IPR=0 and V2bis. Modem stays blocked.
Received FAX page can be shorter and confuse than the normal page.