

Software Release Note AT Version Vx40a Class B GPRS Release

1 New Features

None.

2 Corrected Problems (CP) / Changes in the AT command Description (AT)

Type	Title
CP	All conditionnal CF registration with No Reply conditon timer
CP	CSSN : Wrong unsolicited result code when call hold is released
CP	BAIC : Bad +CLCK response when activating All Teleservices
CP	Incorrect +CRING info displayed in specific cases
CP	AT+CLCK will activate/deactivate call barring --all Basic Services
CP	SMS longer than 160 characters sent and badly truncated
CP	It occurs that there are no response to escape sequence +++.
AT	wrong description of the command +WCDP in the AT document
CP	SIM Phone book status (+WIND) is wrong after removing one or more records.
CP	wm_ioRead API problem
CP	Bad error report on out of range tone value for DTMF sequence (+VTS)
CP	AT+VIP=1 also restores controler factory settings (AT DOC)
AT	update needed for GSM sequences for call forwarding in AT doc
AT	Lack of details about WFM features in AT document
CP	The module sends AT response twice
CP	pb with the command +WDTMF with the 540_09gg.Q24x6B 1378272 122402 13:17
CP	No difference between '*' and '1' for the +WDTMF on the 540
CP	Defective behavior of Default Player
CP	Explicit call transfert with second call alerting
CP	#7854: SMS in PDU mode read failure, the 54th SMS is not read corectly
CP	CPIN , CKPD: No response after PIN modification attempt
CP	AT+IPR=0 return strange character
CP	AT+WBCM=0 can't stop charging

Type	Title
AT	AT+CGDCONT stored in E2P: table 19.10 not updated
CP	cannot dial atd*99***1# if PIN2 is entered
CP	AT+WIMEI erase IP feature
CP	Data transmission is interrupt and data can be lost during the transf (dup #9536
CP	AT+VTS=? no more supported (unexpected CME ERROR: 4)
CP	Customer Feature removed after imei download with production tools

3 Known Bugs

Title
CGREG :5 is returned without any change in MT's GPRS network registration
CGREG: bad cgreg indication after changing mobile class
RING indication is unreadable when IPR=0 and DTE= 57600.
Disable the supplementary CELL UPDATEs optimization for FTA
BAIC : Bad +CLCK response when interrogate call barring of incoming calls
FDIS: bad syntax error management
FDCC: bad syntax error management
+CREG: 2
AT+CPIN=<puk>,<pin_too_long>